## **Core Acceptance Policy**

Customers wishing to obtain refunds on their purchase of BBI re-manufactured injectors, customer will be charged an up front core deposit. Customers core injectors have to be received within 30 days of the original invoice date.

Upon return and thorough inspection of core injectors, customer will be refunded either the full or a partial pro-rated core deposit.

The amount of the refund is affected by many factors.

**BIG BANG** 



INJECTION

Big Bang Injection will accept all returned cores with NO VISUAL damages on the injector's outside. The following visual failures will lead to a reduced core value.



## Broken Magnet Pin ( - \$45.00 )

Broken Magnet Clip ( - \$45.00 )

Modified Inj Flange ( -\$60.00 )







Heavy Corrosion (No Core Value)
\*This type of outside corrosion is due to water contamination of the fuel.

\* This is the internal damaged caused by water contamination \*





NOTE: If you see rust on the outside of the injector body in the area where the injector is in contact with the backflow of the injector (below the O-Ring, exactly where you see it on this specific injector) the internals of the injector are contaminated also.

BBI cannot reuse any parts with rust on them as corroded spots reduce the tensile strength of parts and harm the functionality.

Additionally to the damage shown above, the amount of the refund can be affected:

- Fire Damage
- Missing or destroyed injector internals caused by disassembling the injector.